


# Investigation results of the Unit 1 pedestal floor

Tokyo Electric Power Company (TEPCO) Holdings, Inc. investigated the pedestal opening. The first-half investigation on March 2022 confirmed that the pedestal wall of the opening part was damaged. The second-half investigation on March 2023 confirmed that the entire circumference of the pedestal interior was also damaged.

- TEPCO assumes that the lost concrete area of the pedestal inner wall (only concrete remains) is approximately 1 meter in height and 50cm in depth.
- The lost of the pedestal outer wall opening would be limited.



A ROV frame can be seen,



Photo 1: Concrete remains seen from the pedestal opening

Photo 2: Concrete remains seen from the pedestal opening

Photos processed by TEPCO Holdings Inc.

FRONT (WAT)

# 水中監視カメラ

2023/03/29  
11:42:45

(ポイ)